The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original and First Copy with Department of Ecology
Second Copy — Owner's Copy
Third Copy — Driller's Copy 42200

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No. W57175
UNIQUE WELL I.D. # ABQ 910
Water Right Permit No. ~~99141~~

(1) OWNER: Name Jack & Roberta Wilder Address 3733 Sand Creek Rd. Kettle Falls, Wa.

LOCATION OF WELL: County Stevens NE 1/4 SE 1/4 Sec 27 T. 40 N., R. 36 W.M.

(2a) STREET ADDRESS OF WELL (or nearest address)

(3) PROPOSED USE: [X] Domestic [ ] Industrial [ ] Municipal [ ] Irrigation [ ] Test Well [ ] Other [ ] DeWater

(4) TYPE OF WORK: Owner's number of well (If more than one)
Abandoned [ ] New well [X] Method: Dug [ ] Bored [ ] Deepened [ ] Cable [ ] Driven [ ] Reconditioned [ ] Rotary [X] Jetted [ ]

(5) DIMENSIONS: Diameter of well 6 inches. Drilled 60 feet. Depth of completed well 60 ft.

(6) CONSTRUCTION DETAILS:
Casing Installed: 6 " Diam. from +1 ft. to 55 ft.
Welded [X]
Liner installed [ ] " Diam. from ft. to ft.
Threaded [ ] " Diam. from ft. to ft.

Perforations: Yes [ ] No [X]
Type of perforator used
SIZE of perforations in. by in.
perforations from ft. to ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes [X] No [ ]
Manufacturer's Name Cook
Type stainless Model No.
Diam. 5 Slot size #14 from 55 ft. to 60 ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes [ ] No [X] Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes [X] No [ ] To what depth? 19 ft.
Material used in seal bentonite
Did any strata contain unusable water? Yes [ ] No [X]
Type of water? Depth of strata
Method of sealing strata off

(7) PUMP: Manufacturer's Name
Type: H.P.

(8) WATER LEVELS: Land-surface elevation above mean sea level ft.
Static level 15 ft. below top of well Date 9/27/94
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
Was a pump test made? Yes [ ] No [X] If yes, by whom?
Yield: gal./min. with ft. drawdown after hrs.
" " " "
" " " "
Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test
Bailer test gal./min. with ft. drawdown after hrs.
Airtest 30+ gal./min. with stem set at 58 ft. for 1 hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes [ ] No [X]

(10) WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
overburden	0	2
sand & gravel	2	25
sand & water	25	45
sand, gravel, & water	45	60

DEC - 9

Work Started 9/27/94 19. Completed 9/27/94 19

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME FOGLE PUMP & SUPPLY, INC. (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address 316 W. 5th Colville, Wa. 99114

(Signed) Mike Fogle (WELL DRILLER) License No. 1451

Contractor's Registration No. FOGLEPS095L4 Date 9/27/94 19

(USE ADDITIONAL SHEETS IF NECESSARY)

Ecology is an Equal Opportunity and Affirmative Action employer. For special accommodation needs, contact the Water Resources Program at (206) 407-6600. The TDD number is (206) 407-6006.

ECY 050-1-20 (9/93) * * f