


Within the SW1/4 of Section 19,
T. 37 N., R. 32 E., W.M., FERRY COUNTY, WASHINGTON



Found section corner. (See Ref. 1)
 Found quarter section corner. (See Ref. 1)
 Found existent corner. (See Ref. 1)
 Set corner this survey: A 5.8" x 24" rebar
 with 2" alum. cap #20865
 Set Point on Line at indicated distance

- Found section corner. (See Ref. 1)
 Found quarter section corner. (See Ref. 1)
 Found existent corner. (See Ref. 1)
 Set corner this survey: A 5.8" x 24" rebar
 with 2" alum. cap #20865
 Set Point on Line at indicated distance

[illegible][illegible][illegible][illegible][illegible]

This page correctly represents a source, but does not include any direction or assistance with the Researching Act or the request of

Walden Avenue, in January of 2006

Grand D. Taylor, P.S. Certificate No. 2006

SECRET

**MID-
MOUNTAIN
SURVEYORS, INC.**

*Leads in Tucson
Professional Land Surveying
& Certified Federal Surveyors (1 Fed's)*

AUDITOR'S CERTIFICATE:
 Found no record this _____ day of _____
 State at _____ to page _____ Book _____
 of Short Pass as the request of William Needie
AUDITOR'S FILE NO _____
 Donee Garret Ferry County Auditor

1" = 160'

BASIS OF BEARING:
as Measured from the Guide, Fixing
Station (G.F.S.) as indicated in the North Quarter
corner of Section 16 per Foot.